

Inspection Photos

API: 009-06268

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/6/2022

Inspection Photos



Photo 1. Facing east toward the tank battery along the access road. Sign does not reflect current Operator or emergency contact INFO. If take is not in use it must be removed. Tank berm is inadequate.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/6/2022

Inspection Photos



Photo 2. Facing toward the well site. There is weed debris near the pumpjack which is a fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/6/2022

Inspection Photos



Photo 3. Well sign does not reflect current Operator or emergency contact INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/6/2022

Inspection Photos



Photo 4. There was a water leak observed at intersection of CR X and 51. There is a meter run located at red arrow 1500 Ft. SW of well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06268 | Date: 5/6/2022

Inspection Photos



Photo 5. There is a meter run located on the southeast corner of CR X and 51.



Photo 6. Sign INFO does not have valid emergency contact.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources