

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2022

Submitted Date:

05/09/2022

Document Number:

690202880

FIELD INSPECTION FORM

Loc ID 321045 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------|---------|
| Kosola, Jason | | jason.kosola@state.co.us | |
| Levengood, John | | jlevengood07@gmail.com | |
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| LEVENGOD SARAH | | doveratwoodcorp@yahoo.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|---------------------|-------------|
| 205853 | WELL | PR | 05/01/2020 | GW | 009-06268 | ROBBINS RANCH 'C' 1 | RI |
| 480585 | TANK BATTERY | AC | 08/26/2021 | | - | Robbins Ranch Tank | RI |

General Comment:

[This is a reclamation inspection of the tank battery and wellsite.](#)
[See attached photos and additional details within this report.](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---|-------|------------|
| Type | BATTERY | | |
| Comment: | Sign does not reflect current Operator or emergency contact INFO. Sign not posted or information inaccurate at battery | | |
| Corrective Action: | Install sign to comply with Rule 605.e. | Date: | 06/09/2022 |
| Type | WELLHEAD | | |
| Comment: | Sign does not reflect current Operator or emergency contact INFO. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 06/09/2022 |

Emergency Contact Number:

| | | | |
|--------------------|---|-------|--|
| Comment: | The emergency contact number was not valid. | | |
| Corrective Action: | | Date: | |

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Tank is labeled NOT IN USE. All unused equipment needs to be removed. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 06/09/2022 |
| Type | DEBRIS | | |
| Comment: | There is weed debris around the equipment which needs to be removed. | | |
| Corrective Action: | Comply with Rule 610. Comply with Rule 606. | Date: | 05/13/2022 |

Overall Good:

Spills:

| Type | Area | Volume | |
|--------------------|--|-----------|------------------|
| Produced Water | Flow Line | >= 5 bbls | |
| Comment: | Leak observed along the flowline at intersection of CR 51 and X. Operator notified by phone call. | | |
| Corrective Action: | Report spill or release of E&P waste or produced fluids. Remove free fluids and contact COGCC EPS staff per Rule 912.b. | | Date: 05/10/2022 |

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|------|---------|--------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|-----------------|----------------------|
| Condition | <input type="text"/> |
| Other (Content) | <input type="text"/> |

| | |
|------------------|--|
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|------------------|
| Earth | Inadequate | Walls Insufficient | | Inadequate |
| Comment: | The berm around the tank is inadequate to contain a spill. The tank needs to be removed if not in use or the berm around the tank needs to be repaired. | | | |
| Corrective Action: | Repair or install berms or other secondary containment devices per Rule 603.o. | | | Date: 06/09/2022 |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 690202881 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747891 |