

Inspection Photos

API: 009-06174

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/6/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022

Inspection Photos



Photo 1. Facing northeast toward the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022

Inspection Photos



Photo 2. There is unused debris, cement blocks, and metal pipe laying on the grounding interfering with farming operations. Lat/Long:37.32092,-102.15106.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022

Inspection Photos



Photo 3. Facing toward the well site in cropland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022

Inspection Photos



Photo 4. The well sign is inaccurate and reflects the wrong Operator info and emergency contact INFO.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022

Inspection Photos



Photo 5. There is a gate and unused supplies lying on the ground. There is no cover for the electric utility which is a safety concern.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 009-06174 | Date: 5/6/2022