

APACHE CANYON 10-16V API# 05-071-07560 – OGRIS OPERATING
OGCC OPERATOR NUMBER 10758 - DATE: MAY 09, 2022
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT #690202042



PHOTO 1: THE MAIN LEASE ROAD WAS SURFACE CROWNED TO REMOVE THE TIRE RUTS AND ESTABLISH SHEET FLOW.



PHOTO 2: THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE LOW SPOT AND ESTABLISH SHEET FLOW.




PHOTO 3: THE MAIN LEASE ROAD SURFACE WAS CROWNED TO REMOVE THE LOW SPOT AND ESTABLISH SHEET FLOW




PHOTO 4: THE WELL PAD WAS
REGRADED TO REMOVE THE TIRE RUTS.



PHOTO 5: THE IMPACTED SOIL NEAR THE LIQUID RING COMPRESSOR WAS CLEANED UP AND REMOVED FROM LOCATION. THE INSULATION DEBRIS HAS BEEN PICKED UP AND REMOVED FROM LOCATION AS WELL. THE SELF INSPECTION PROCESS HAS BEEN REVIEWED.