

# Inspection Photos

API: 009-06082

Operator: DOVER ATWOOD CORPORATION

Inspection Date: 5/6/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022

## Inspection Photos



**Photo 1.** Facing east toward the location. The door to the meter shed is in disrepair and laying on the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022

## Inspection Photos



**Photo 2.** Missing tank NFPA labeling and missing INFO per 605.h.. Secondary containment is inadequate to contain 150% of the volume of the tank. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022



## Inspection Photos



**Photo 3.** View of fluids inside the tank. Tank is labeled Produced Water. It appears to be solidified salty produced water. The netting on the tank is in disrepair. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022



## Inspection Photos



**Photo 4.** There appears to have been a leak at the tank due to stained soil in this area. If tank contains produced salty water, this can impact the soil and crop growth. Previous corrective action not completed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022

## Inspection Photos



**Photo 5.** Well sign is posted at wellhead. Emergency contact number is not valid.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 009-06082 | Date: 5/6/2022