

Inspection Photos
Location Name: 100 WCR Group 14-11-8-61
Location ID: 425364



Photo 1 – Pumping Unit

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: 100 WCR Group 14-11-8-61
Location ID: 425364



Photo 3 – Stained Soil at Exhaust




Photo 4 - Unused Valve and Stained Soil

Inspection Photos
Location Name: 100 WCR Group 14-11-8-61
Location ID: 425364



Photo 5 – Stained Soil at Wellhead

Photo 6 – ECDs

Inspection Photos
Location Name: 100 WCR Group 14-11-8-61
Location ID: 425364





Photo 7 – Labels fading

Photo 8 – Labels fading

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225




Photo 9 – ECD and Flare

Photo 10 – Tank Battery Sign

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 11 – Heater Treater