

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/06/2022

Submitted Date:

05/10/2022

Document Number:

699603051

**FIELD INSPECTION FORM**Loc ID 428637 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430337	TANK BATTERY	AC	03/13/2012		-	Siebring Pad 5-63-32-16H	IO

**General Comment:**

This is a TANK BATTERY inspection.  
Battery: Inactive | Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID  
(430337).

Centralized Battery serves 5 Location IDs  
(306088, 332148, 332236, 332237, 332267).  
(Well(s): 5: Temporarily Abandoned | TA).

-Refer to Field Inspection Report doc. #699603053 and/or Location ID #332237 for Well(s) info.  
Well(s): 1: Temporarily Abandoned | TA.

-Refer to Field Inspection Report doc. #699603055 and/or Location ID #306088 for Well(s) info.  
Well(s): 1: Temporarily Abandoned | TA.

-Refer to Field Inspection Report doc. #699603057 and/or Location ID #332148 for Well(s) info.  
Well(s): 1: Temporarily Abandoned | TA.

-Refer to Field Inspection Report doc. #699603059 and/or Location ID #332236 for Well(s) info.  
Well(s): 1: Temporarily Abandoned | TA.

-Refer to Field Inspection Report doc. #699603061 and/or Location ID #332267 for Well(s) info.  
Well(s): 1: Temporarily Abandoned | TA.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methanol.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: _____

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Surrounded by earth berms.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pig Station	# 0		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 0		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	At Battery site: Methanol tank w/ drip containment. Placards.	
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:	Calibration card indicates calibration within last year. Last calibration: 07/21/2021. Inactive, no production.	
Corrective Action:		Date:
Type: Emission Control Device	# 0	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (430337). Centralized Battery serves 5 Location IDs (306088, 332148, 332236, 332237, 332267). (Well(s): 5: Temporarily Abandoned   TA).				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Inspector Name: Evins, Bret

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: <a href="#">Shares berms w/ crude oil tanks.</a>					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	3	300 BBLS	STEEL AST		40.363010,-104.450910	
Comment:						
Corrective Action:						
Date:						

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment: <a href="#">Shares berms w/ produced H2O tank.</a>					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:	Date:		

**Flaring:**

Type			
Comment:			
Corrective Action:	Date:		



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 05/06/2022 at approximately 12:13 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: HIGHPOINT OPERATING CORPORATION  Facility Name: Siebring Pad /5-63-32-16H  Facility ID: 430337  Location Name: Siebring /5-63-32 NE  Location ID: 428637  Well Name(s):  Siebring 41-32, Siebring 32-32, Siebring 42-32, Siebring 31-32, Siebring CNE-32.  API: 05-123-22021, 05-123-21903, 05-123-22020, 05-123-22062, 051-123-23967.  Location County: Weld County, Colorado  Weather: Partly Sunny w/ haze, damp from prior storm.</p> <p>While there, I observed:  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (430337).  Centralized Battery serves 5 Location IDs (306088, 332148, 332236, 332237, 332267).  (Well(s): 5: Temporarily Abandoned   TA).</p> <p>-Refer to Field Inspection Report doc. #699603053 and/or Location ID #332237 for Well(s) info.  Well(s): 1: Temporarily Abandoned   TA.  -Refer to Field Inspection Report doc. #699603055 and/or Location ID #306088 for Well(s) info.  Well(s): 1: Temporarily Abandoned   TA.  -Refer to Field Inspection Report doc. #699603057 and/or Location ID #332148 for Well(s) info.  Well(s): 1: Temporarily Abandoned   TA.  -Refer to Field Inspection Report doc. #699603059 and/or Location ID #332236 for Well(s) info.  Well(s): 1: Temporarily Abandoned   TA.  -Refer to Field Inspection Report doc. #699603061 and/or Location ID #332267 for Well(s) info.  Well(s): 1: Temporarily Abandoned   TA.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/10/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699603052	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749952">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5749952</a>

