

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/03/2022

Submitted Date:

05/04/2022

Document Number:

701103034

FIELD INSPECTION FORMLoc ID 314347 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 77900

Name of Operator: SHAWNEE OIL DEVELOPMENT CO INC

Address: P O BOX 300

City: KEVIN State: MT Zip: 59454

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Hawkins, Jim	406-873-5277	jhawkins@bresnan.net	
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228480	WELL	SI	01/01/2022	OW	103-05338	CHURCH ET AL 1	SI

General Comment:

COGCC Routine Inspection Report Summary

During this inspection the following compliance issues were observed:

- Locked gate at access.

On 3/31/2022 Inspector Mike Longworth emailed operator Jim Hawkins for key or combination to gain access to location. Response from operator was that the pumper would contact inspector with key or combination. No contact has been made from pumper.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location**Lease Road:**

Type	Access		
comment:	Locked gate at access. On 3/31/2022 Inspector Mike Longworth emailed operator Jim Hawkins for key or combination to gain access to location. Response from operator was that the pumper would contact inspector with key or combination. No contact has been made from pumper.		
Corrective Action:	Provide key, combinations, or alternate method of access to comply with rule 204.	Date:	05/05/2022

Overall Good: ☐**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 228480 Type: WELL API Number: 103-05338 Status: SI Insp. Status: SI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403038650	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745105
701103035	Inspection 701103034 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745102