

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2022

Submitted Date:

05/04/2022

Document Number:

700901115**FIELD INSPECTION FORM**Loc ID 319714 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #225City: AURORA State: CO Zip: 80016**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
		dnr_cogccenforcement@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201072	WELL	PR	10/01/2020	OG	001-06475	FERGUSON 2-25	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	605.d. Signs and Markers on Pump Jack.		
Corrective Action:	Corrective Action Date 6/8/2022. See attached photo # 10.	Date:	07/06/2022

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:	Rule 606.(Trash used plastic buckets in separator house).		
Corrective Action:	Corrective Action Date 5/25/2022. See attached photos # 4 & 5	Date:	05/25/2022

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment: Rule 603.o.(1) Inadequate / unmaintained berms around tank(s) (base under Produced water tank)				
Corrective Action: Corrective Action Date 6/8/2022. See attached photo # 7.				Date: 06/08/2022

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		39.847863,-104.274360
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
001-06499
001-08792
001-06482
001-06475
001-06501
001-06513
001-06523

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities

Facility ID: 201072 Type: WELL API Number: 001-06475 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: _____ Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: Appears to be plumbed to surface

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday May 4, 2022 at approximately 9:45am. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: RENEGADE OIL & GAS Well Name: Ferguson 2-25 API #: 001-06475 Location ID#: 319714 County: Adams While there, I observed a Producing well. During this inspection the following possible compliance issues were observed: Rule 603.o.(1) Inadequate / unmaintained berms around tank(s) (base under Produced water tank) Corrective Action Date 6/8/2022. See attached photo # 7. Rule 606.(Trash used plastic buckets in separator house.) Corrective Action Date 5/25/2022. See attached photos # 4 & 5. Rule 909.d. Hydrocarbons observed on pit. Corrective Action Date 6/8/2022. See attached photo # 9. Rule 605.d. Signs and Markers on Pump Jack. Corrective Action Date 6/8/2022. See attached photo # 10.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	05/04/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403038788	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745306
700901116	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745303