

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2022

Submitted Date:

05/09/2022

Document Number:

690202882

FIELD INSPECTION FORM

Loc ID 321008 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10626
Name of Operator: DOVER ATWOOD CORPORATION
Address: 1875 HARSH AVENUE SE
City: MASSILLON State: OH Zip: 44646

Findings:

- 5 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
LEVENGOOD SARAH		doveratwoodcorp@yahoo.com	
Levengood, John		jlevengood07@gmail.com	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205762	WELL	PR	05/01/2020	GW	009-06174	TRAHERN 'A' 1	RI
479922	TANK BATTERY	AC	05/05/2021		-	Trahern Tank A-1	RI

General Comment:

[This is a reclamation inspection of the tank battery and wellsite.](#)
[See attached photos and additional details within this report.](#)

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Sign does not reflect current Operator or emergency contact INFO.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/09/2022

Emergency Contact Number:

Comment:	The emergency contact number was not valid.		
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	There is a gate and unused supplies laying on the ground. There is no cover for the electric utility which is a safety concern.		
Corrective Action:	Comply with Rule 606.	Date:	05/13/2022
Type	DEBRIS		
Comment:	There is unused debris, cement blocks, and metal pipe laying on the ground interfering with farming operations. Lat/Long:37.32092,-102.15106. Must be removed.		
Corrective Action:	Comply with Rule 606.	Date:	05/13/2022

Overall Good:

Spills:

Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403041984	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747991
690202883	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5747989