

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/16/2022

Submitted Date:

05/18/2022

Document Number:

702500039

**FIELD INSPECTION FORM**
 Loc ID 325849 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
General		sjninspections@ikavenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215468	WELL	PR	10/01/2019	GW	067-07073	FISCHER-MARK FEDERAL B 1	PR
450653	WELL	PA	11/20/2018	LO	067-10002	FISCHER-MARK FEDERAL B 5	PA

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

### Location

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water tank sign visible and legible (IMG 15).		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	Emergency number listed on sign at site entrance (IMG 01).
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Tree has fallen on southern edge of location (IMG 07).		
Corrective Action:	Remove from pad to comply with rule 606.	Date:	06/08/2022

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Site is enclosed by barb wire fencing.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	# 4		
Comment:	3" Line from wellhead to separator, 3" line from separator to meter house, 3" line from separator to produced water tank, 1" line from wellhead to pump jack generator (IMG 12).		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	Tylemetry, pump control panel, and buried valve cluster pit.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Separator vent stack properly screened (IMG 13).		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.238547,-107.527226
Comment:	Partially buried produced water tank (IMG 10).				
Corrective Action:				Date:	

**Paint**

Condition	Adequate	
Other (Content)	Produced water	
Other (Capacity)	95 bbls	
Other (Type)	Cone top	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal berm for produced water tank.			
Corrective Action:			Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	215468	Type:	WELL	API Number:	067-07073	Status:	PR	Insp. Status:	PR
Facility ID:	450653	Type:	WELL	API Number:	067-10002	Status:	PA	Insp. Status:	PA

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Pass					
Ditches	Pass					
		Culverts	Pass			
Rip Rap	Pass					

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Wildlife BMP's appear sufficient. All openings and vents are screened.</span>	klinka	05/16/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500042	Photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757129">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757129</a>