

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/17/2022

Submitted Date:

05/18/2022

Document Number:

701103119

FIELD INSPECTION FORM

Loc ID 321999 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
11 Number of Comments
5 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10515
 Name of Operator: GUNNISON ENERGY LLC
 Address: 1801 BROADWAY #1150
 City: DENVER State: CO Zip: 80202

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Lang, Heather		Heather.Lang@oxbow.com	
,		geops@oxbow.com	Inspection mail box
Donahue, Jessica		jdonahue@ardorenvironmental.com	Compliance Specialist
Johnston, Tyson		Tyson.Johnston@oxbow.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272542	WELL	SI	09/01/2005	GW	029-06087	SPAULDING PEAK 1294 23-33	TA

General Comment:

[COGCC Follow Up Inspection Report Summary](#)
 Follow up to [7/22/2020 inspection # 699801486](#), [6/23/2021 inspection # 701101636](#), and [10/01/2021 inspection # 701102026](#)
 Corrected action item
 • 911 written on sign with maker
 Uncorrected action item(s)
 • Last MIT [7/7/2016 Doc# 2226183](#) (over 5 years) No current form 4 requesting temporarily abandoned status.
 • Unused shed and 15 flowline risers.
 During this inspection the following compliance issues were observed:
 • Debris from demolition of shed wall to remove surface equipment.
 • Staining of ground surface under shed that surface equipment was removed from
 • Telephone number for local emergency services (911 where available); and The public road used to access the Well are written on well sign and are faded/faint. No API # on well sign. Sign has a disconnected operator number.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Telephone number for local emergency services (911 where available); and The public road used to access the Well are written on well sign and are faded/faint. No API # on well sign. Sign has a disconnected operator number.		
Corrective Action:	Install sign to comply with Rules 605.d. and 605.g.		Date: <u>08/20/2022</u>
Emergency Contact Number:			
Comment:	<input type="text" value="911 added to sign at well head."/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris from demolition of shed wall to remove surface equipment.		
Corrective Action:	Comply with Rule 606		Date: <u>06/03/2022</u>
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location. Unused shed and 15 flowline risers.		
Corrective Action:	Comply with Rule 606		Date: <u>10/22/2021</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
	Flow Line	<= 1 bbl	
Comment:	Staining of ground surface under shed that surface equipment was removed from.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: <u>06/20/2022</u>
In Containment: <u>No</u>			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 15		
Comment:	15 flow line risers under derelict shed.		
Corrective Action:			Date:
Venting:			

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 272542 Type: WELL API Number: 029-06087 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT 7/7/2016 Doc# 2226183 (over 5 years)
Last MIT preformed 7/7/16. No current form 4 requesting temporarily abandoned status.

Corrective Action: A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. submit form 4.
A Sundry Notice, Form 4, or other form approved by the Director, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation. submit form 4.
Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or
2) Be properly plugged and abandoned.
3) A sundry requesting continued temporarily abandoned status should be submitted to COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere.
Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 08/22/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						
Compaction						
Check Dams						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701103121	Inspection 701103119 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5757460