

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2022

Submitted Date:

05/12/2022

Document Number:

699804497

**FIELD INSPECTION FORM**

Loc ID 334948 Inspector Name: De Paolo, Corey On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 13 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274126	WELL	PR	03/27/2005	OW	045-13338	WILLIAMS GM 544-1	PR
274128	WELL	PR	03/30/2005	GW	045-13337	WILLIAMS GM 344-1	PR
274129	WELL	PR	10/14/2004	OW	045-13336	WILLIAMS GM 444-1	PR

**General Comment:**

[COGCC Inspection Report Summary](#)  
On Thursday 5/12/22 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at TEP ROCKY MOUNTAIN LLC WILLIAMS-67S96W /1SESE. Location #334948 in Garfield County Colorado. Refer to document #699803578 inspection conducted on 8/18/21. Previous corrective actions have been completed. While there, I observed normal production operations. During this inspection the following compliance issues were observed:

1) Wellhead sign weathered and not legible with a corrective action date of 7/12/22.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Wellhead sign weathered and not legible.		
Corrective Action:	Operators will ensure that signs are well maintained and legible, and will replace damaged signs.	Date:	07/12/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 3		

Comment:	No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible.			Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 3				
Comment:	All wells on plunger lift			Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:				Date:	
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		
		Date:

**Inspected Facilities**

Facility ID: 274126 Type: WELL API Number: 045-13338 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 274128 Type: WELL API Number: 045-13337 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

Facility ID: 274129 Type: WELL API Number: 045-13336 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
		Berms				
		Sediment Traps				
Compaction						
Sediment Traps						
Gravel						
Berms						
		Gravel				
Other						
		Culverts				
		Ditches				
		Sediment Traps				

Comment: Location appears to have some gravel throughout the location with light compaction. Places with light to no gravel are present on location. Light gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Sign/Markers for corrective actions.</a>	depaoloc	05/12/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403049134	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753575">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753575</a>
699804498	Photos for Insp. #699804497	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753572">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753572</a>