

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2022

Submitted Date:

05/13/2022

Document Number:

700704187**FIELD INSPECTION FORM**Loc ID 323783 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		bcoutts@mustangresourcesllc.com	
, mustang	303-807-5112	dlemon@mustangresourcesllc.com	regulatory manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210798	WELL	PR	12/01/2016	GW	045-06556	MEAD 23-44-6S-94W	PR

General Comment:**COGCC Inspection Report Summary**

On Thursday 5/12/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at Mustang Mead 23-44, at Location # 323783 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management.

During this inspection the following possible compliance issues were observed:

1. Some areas of location show signs of lack of stabilization/ compaction/ degradation/ erosion.
2. Production tank missing quantity.
3. Staining.
4. Catch tank full of fluid and has a hole.
5. Stored piping.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Production tank missing quantity.		
Corrective Action:	Provide proper labeling.	Date:	05/27/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Stored piping.		
Corrective Action:	Remove stored equipment.	Date:	06/24/2022
Type	OTHER		
Comment:	Random staining		
Corrective Action:	Remove stained material	Date:	06/24/2022
Type	OTHER		
Comment:	Catch tank full of fluid and has a hole.		
Corrective Action:	Evacuate fluids in containment and repair hole or replace containment.	Date:	05/20/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	1 500 gallon oil tank in metal containment and 1 chemical tank in metal containment.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		STEEL AST		,
Comment:	Production tank missing quantity. See labeling C/A				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:				
Corrective Action:				Date:

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities			
Facility ID: 210798	Type: WELL	API Number: 045-06556	Status: PR
Insp. Status: PR			
Producing Well			
Comment:	Producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail					

Comment: [1. Some areas of location show signs of lack of stabilization/ compaction/ degradation/ erosion. Sediment migration from location.](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 06/24/2022

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403049466	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753839
700704197	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5753830