

## Inspection Photos

Location Name: M & M #1, #2, #3 & #4 Battery

Location ID: A location ID is being generated



**IMG 01**  
**Well Sign**



**IMG 02**  
**Site Overview**

## Inspection Photos

Location Name: M & M #1, #2, #3 & #4 Battery

Location ID: A location ID is being generated



**IMG 03**

**Standing residual oily fluid In tank**



**IMG 04**

**Standing residual oily fluid In tank**

## Inspection Photos

Location Name: M & M #1, #2, #3 & #4 Battery

Location ID: A location ID is being generated



**IMG 05**

**Tank marked both as both crude and produced water, NFPA placard is deteriorated,**



**IMG 06**

**Site photo**

**Inspection Photos**  
**Location Name: M & M #1, #2, #3 & #4 Battery**  
**Location ID: A location ID is being generated**



**IMG 07**  
**Site photo**



**IMG 08**  
**Empty 55 gallon drums**

Inspection Photos  
Location Name: M & M #1, #2, #3 & #4 Battery  
Location ID: A location ID is being generated



**IMG 09**  
Tank battery



**IMG 10**  
Wildlife burrows in secondary containment berms

## Inspection Photos

Location Name: M & M #1, #2, #3 & #4 Battery

Location ID: A location ID is being generated



**IMG 11**

**Wildlife burrows in secondary containment berms**



**IMG 12**

**Separator**

## Inspection Photos

Location Name: M & M #1, #2, #3 & #4 Battery

Location ID: A location ID is being generated



**IMG 13**  
**Separator**