

Inspection Photos
Operator: Hilcorp Energy
API: 067-05815
Date: 5/24/2022



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope. Little desirable vegetation observed on the slope.



Photo 3. View of area at the well pad entrance with bare soils needing stabilization.



Photo 4. View of reference area vegetation comprised of open grass field with a mix of native and non-native grasses and forbs such as western wheatgrass, purple mustard, and flixweed.