

Inspection Photos
Operator: Hilcorp Energy
API: 067-08186
Date: 5/24/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing within crested wheatgrass, smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of area within the northern interim reclamation area where tire tracks observed and are resulting in site degradation.



Photo 5. View of rutting, approximately 12 to 18 inches deep on the well pad surface. Additional stabilization is needed here.



Photo 6. View of salt cedar at the entrance to the access road need to be removed and controlled.



Photo 7. View of reference area comprised of pinyon and juniper woodland with sagebrush, Indian ricegrass, antelope bitterbrush, mountain mahogany, and sulfur flower.