

Inspection Photos

Operator: Hilcorp Energy
API: 067-08350
Date: 5/24/2022



Photo 1. View of the project area from the western entrance facing center. .



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing within crested wheatgrass, smooth brome, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of dense Russian knapweeds observed along the western access and throughout the interim reclamation areas. Thousands of individuals observed.



Photo 4. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing in non-weedy portions with western wheatgrass, and crested wheatgrass.



Photo 5. Another view of Russian knapweeds, this is along the western access road.



Photo 6. View of reference area comprised of pinyon and juniper woodland with gambel oak, Indian ricegrass, antelope bitterbrush, mountain mahogany, and sulfur flower.