

Inspection Photos
Operator: Hilcorp Energy
API: 067-08223
Date: 5/24/2022



Photo 1. View of the project area from the southeastern entrance facing center. .



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing within crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of dense Russian within the southern project area. Approximately 2000 individuals observed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, Indian ricegrass, antelope bitterbrush, mountain mahogany, and sulfur flower.