

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION ENERGY MINING DIV.-66S96W /33NESE

Location ID: 335267



Photo #6794 from entrance to location.



Photo #6795 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION ENERGY MINING DIV.-66S96W /33NESE

Location ID: 335267



Photo #6796 Loadline open ended.



Photo #6797 Vent pipe open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION ENERGY MINING DIV.-66S96W /33NESE

Location ID: 335267



Photo #6798 Location lacks stabilization.



Photo #6799 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION ENERGY MINING DIV.-66S96W /33NESE

Location ID: 335267



Photo #6800 Insufficient tracking BMP located at the entrance to location.