

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /33NENE

Location ID: 335435



Photo #6807 from entrance to location.



Photo #6809 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /33NENE

Location ID: 335435



Photo #6810 Debris on location.



Photo #6813 Debris on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /33NENE

Location ID: 335435



Photo #6811 Loadline open ended.



Photo #6808 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /33NENE

Location ID: 335435



Photo #6814 Location lacks stabilization.



Photo #6815 Rill erosion occurring on location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /33NENE

Location ID: 335435



Photo #681 Sediment encroaching on tank containment.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources