

TEP
Gentry
Location # 311695



location



location

TEP
Gentry
Location # 311695



location



Staining

TEP
Gentry
Location # 311695



Staining



Debris



Previous inspection photo taken from the well equipment facing west shows BMPs to prevent wildlife access to the well cellars were missing or insufficient.

**TEP
Gentry
Location # 311695**



Recent photo show C/A has not been completed

TEP
Gentry
Location # 311695



Fencing is also open to well heads



Fencing is also open to well heads

TEP
Gentry
Location # 311695



Pot hole trench is showing subsidence



Pot hole trench is showing subsidence



Previous inspection photo taken from the north of the Location facing north shows undesirable plant species/weed debris accumulating in production areas. Photo from reclamation inspector

**TEP
Gentry
Location # 311695**



Recent inspection show C/A has not been completed




Photo taken from the well equipment facing west shows undesirable plant species/weed debris accumulating in production areas. Photo from reclamation inspector

**TEP
Gentry
Location # 311695**



Recent inspection show C/A has not been completed

TEP
Gentry
Location # 311695



Debris



Debris

TEP
Gentry
Location # 311695



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
Gentry
Location # 311695



Debris

