

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/02/2022

Submitted Date:

06/03/2022

Document Number:

702500068**FIELD INSPECTION FORM**Loc ID 306933 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 7125Name of Operator: BEEMAN OIL & GAS LLCAddress: 3401 QUEBEC ST SUITE 9105City: DENVER State: CO Zip: 80207**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Stepp, Sarah		wcciassistant@gmail.com	All SW field inspections
Galloway, Kelly		kgallowaywerc@gmail.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280138	WELL	PR	08/01/2020	OW	067-09070	HUBBS 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Lease Road:			
Type	Access		
comment:	Dirt access road		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type			
Comment:	Well sign displays inaccurate API		
Corrective Action:	Install sign to comply with Rule 605.a.	Date:	07/02/2022

Emergency Contact Number:			
Comment:	Emergency contact: 970-210-2896 and 911		
Corrective Action:		Date:	

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Pump jack enclosed by steel pipe fencing. Combustor enclosed by metal fence.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Electric prime mover		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	2" line from wellhead to combustor, 2" line from wellhead to off site.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Combustor		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:	Combuster hooked up to casing head, not combusting or venting at time of inspection, no current approved Sundry to vent/flare, no gas capture plan of Rule 903 variance in process.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500074	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5770514