

Inspection Photos

API: 055-06190

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 1. Facing west toward the location. The road travels thru the center of the location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 2. Facing northwest toward the location. The cut slope of the location is visible along the right side of photo and a run-on ditch. This area shown in right portion of the photo is not stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 3. Facing southeast at the location. The surface owner is using the location for a debris burn pit.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 4. There is a pipe riser that remains at the surface of the location that needs to be properly abandoned.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 5. There appears to be liner debris at the surface at the southwest side of the pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 6. There are noxious weeds at the location which include Cheat grass, Red stem filaree, Field bind weed, and Jointed Goat grass.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022

Inspection Photos



Photo 7. Facing northeast toward the location. The cut slope of the location is visible along the center of photo and a run-on ditch.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06190 | Date: 6/7/2022