

# Inspection Photos

API: 055-06276

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/7/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** 2005 aerial image showing the access road and location. Red arrow points to area at photo #2. The remainder of the access road to the northeast was not inspected but needs to be evaluated for possible reclamation maintenance.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022

## Inspection Photos



**Photo 2.** This area of the former access road has not re-established vegetation and consists of weeds. Lat/Long:37.48927, -104.83009



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022

## Inspection Photos



**Photo 3.** Facing southwest along the former access road. The remainder of the road has re-established perennial vegetation. There are some areas with Field bind weed which needs to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022

## Inspection Photos



**Photo 4.** Facing southwest toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022

## Inspection Photos



**Photo 5.** Facing west toward the location which was recontoured and reclaimed. There is desirable vegetation established throughout most of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06276 | Date: 6/7/2022