

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2022

Submitted Date:

06/07/2022

Document Number:

702400592

FIELD INSPECTION FORM

Loc ID 302725 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 15 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
300369	WELL	TA	04/03/2019	OW	123-29695	PARAGON X 30-12	TA

General Comment:

(This area is currently blank for general comments.)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>	Date:	

Good Housekeeping:

Type	WEEDS		
Comment:	Weeds growing along NE sides of WH fencing and access rd.		
Corrective Action:	Comply with Rule 606	Date:	06/21/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Ag panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface		
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 4		
Comment:	automation		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	card indicates current calibration		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	53 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:	Shares containment with crude tank			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.104380,-104.715470
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				

Corrective Action:	Date:
--------------------	-------

Wells Served By Facilities Above

AirsID

API Number
123-29695

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 300369 Type: WELL API Number: 123-29695 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA, Form 04(TA)00 Doc # 402634517 1-7-2022 and Form 04(OBJ-TA)00 Doc # 402976527 4-22-2022

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 05/25/2021 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: None

End Surf Csg Pressure: --

Comment: Submit test results to the COGCC

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 6-7-2022 at approximately 1420 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Oxy/Kerr McGee Location name: Paragon X 30-12 API # 05-123-29695 County: Weld Weather: Clear/Cloudy. Location: Dry. While there, I observed a wellsite and tank battery, TA at the time of inspection. Battery is SW of wellsite. During this inspection, I observed no compliance issues: See attached photos. No follow up site inspection is needed to ensure that the addressed Compliance issues comply with COGCC rules.</p>	revasr	06/07/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702400594	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5774477