

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/25/2022

Submitted Date:

06/02/2022

Document Number:

702800269

FIELD INSPECTION FORMLoc ID 314497 Inspector Name: O'Malley, Anna On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Olson, Andrew		AndrewOlson@chevron.com	Principle Agent Wilson Creek
Puechner, Rachel		RPuechner@chevron.com	Decommissioning Advisor Wilson Creek
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
314497	LOCATION	AC			-	WILSON CREEK UNIT-62N94W 2SWNE	RI

General Comment:

On 05/25/2022, Reclamation Specialist O'Malley conducted a follow up inspection to #702800192 at Chevron USA Inc's Wilson Creek Unit-62N94W /2SWNE Location #314497 in Rio Blanco County, Colorado. West Environmental Supervisor, Alex Fischer was also present for the inspection.

The following compliance issues were observed during this inspection:
- Stormwater: Spoil piles present off site

Refer to the "Location," "Stormwater" and "COGCC Comments" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	At the time of this inspection fencing was present around the perimeter of the wellhead excavation.		
Corrective Action:		Date:	

Equipment:

Type: Other	#		corrective date
Comment:	At the time of this inspection the sides of the excavation around the wellhead are gentle enough to allow for wildlife egress.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection #702800192 observed erosion control BMPs on the Location are missing or insufficient. Inspector required Operator to install or repair required BMPs per Rule 1002.f by 6/10/22. It was observed in this inspection straw wattles are present along the downslope perimeter of the Location. This corrective action has been addressed. However, spoil piles are present downslope of the wattle throughout the edge of the Location. Soil continues down the hillside ~30 yards from the Location edge causing offsite degradation. Refer to attached email regarding this issue.

Refer to "COGCC Comments" section for additional "STORMWATER COMMENTS"

Corrective Action: **Comply with 1002.f and remove spoil piles from the hillside downslope of the Location.**

Date: 07/02/2022

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
STORMWATER COMMENTS	omalleya	06/02/2022
Previous inspection #702800192 observed BMPs to prevent soil piles potentially contaminated with E&P waste from migrating offsite were absent. Inspector required Operator to comply with Rule 913.b.(5).B.i-v by 5/13/22. It was observed in this inspection that wattles have been installed around the downslope perimeter of 2 soil piles. This corrective action has been addressed.		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403066785	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769536
702800270	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769533
702800271	Email Correspondence	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5769534