

# Inspection Photos

API: 055-06306

Operator: MANZANO LLC

Inspection Date: 6/7/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing northwest toward the access road and the location. Red arrow points the the access road and yellow arrow points to the location which have not been reclaimed per rule 1004. Photo taken on 10/5/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 2.** Facing toward the access road the beginning of the access road. The cattleguard remains and the road has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 3.** There has been erosion of the road near the stream crossing which has not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 4.** Facing toward the culvert at the stream crossing. The culvert has become exposed due to erosion and has not been repaired.



**Photo 5.** Facing toward the culvert outlet. An erosion gully has formed at the stream crossing of the access road. Red arrow points to a hat for scale.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 6.** Facing north along the access road which has not been recontoured and reclaimed. There are numerous noxious weeds along the road. Noxious weeds shown in this area is Hoary crest and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 7.** Facing northwest toward the fill slope of the location approximately 10 ft. in height. There are numerous noxious weeds growing along the fill slope of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 8.** Facing northwest along the fill slope. There are numerous noxious weeds along the fill slope. Noxious weeds observed include: Common mullien, Musk thistle, Plumeless thistle, and Scotch thistle.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 9.** Facing west toward the location which has not been recontoured and reclaimed. The location is which is approximately 2.3 acres in size.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 10.** Center of the location facing west. The location is not reclaimed and soils are compacted. There are numerous weeds throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 11.** Facing northwest toward the cut slope of the location which is approximately 12 ft. in height.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 12.** Facing southwest toward the cut slope of the location which is approximately 12 ft. in height. There are noxious weeds (Mullein) along the cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 13.** Facing south back toward the access road and the fill slope at the north side of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022

## Inspection Photos



**Photo 14.** Facing south overlooking the location disturbance which is approximately 2.3 acres in size. The location has not been recontoured and reclaimed and is mostly bare of vegetation. Photo taken during previous inspection.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06306 | Date: 6/7/2022