

Inspection Photos
Location Name: UPRR r23 PAN AM D 2
Location ID: 319939



Pic 1 stained soil, mechanical issue with gas motor, trash on location, no BMP under chemical tanks



Pic 2 stained soil, mechanical issue with gas motor, trash on location, no BMP under chemical tanks

Inspection Photos
Location Name: UPRR r23 PAN AM D 2
Location ID: 319939



Pic 3 mechanical issue with wellhead, oil is covering wellhead




pic 4 crypto currency mining equipment

Inspection Photos
Location Name: UPRR r23 PAN AM D 2
Location ID: 319939



Pic 5 ECD



Pic 6 ECD is active

Inspection Photos
Location Name: UPRR r23 PAN AM D 2
Location ID: 319939



Pic 6 internal gas meter run / natural gas generator



Pic 7 Vertical separator, horizontal separator

Inspection Photos
Location Name: UPRR 23 PAN AM D 2
Location ID: 319939



Pic 8 tanks