

Caerus Piceance LLC
C26NW
Location # 335163



Location



location

Caerus Piceance LLC
C26NW
Location # 335163



Location



location

Caerus Piceance LLC
C26NW
Location # 335163



Location



location

Caerus Piceance LLC
C26NW
Location # 335163



Missing caps/plugs



Missing caps/plugs

Caerus Piceance LLC
C26NW
Location # 335163



Leaking valve on tank



Debris

Caerus Piceance LLC
C26NW
Location # 335163



Debris



Lack of stabilization/ compaction

Caerus Piceance LLC
C26NW
Location # 335163



Lack of stabilization/ compaction



Lack of stabilization/ compaction



Caerus Piceance LLC
C26NW
Location # 335163



Lack of stabilization/ compaction



Lack of stabilization/ compaction

