

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2022

Submitted Date:

06/06/2022

Document Number:

699503999

FIELD INSPECTION FORMLoc ID 320245 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 3990

Name of Operator: ARGONEX COMPANY LLC

Address: PO BOX 810

City: SEDALIA State: CO Zip: 80135

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HARTMAN, LARRY	936-590-1179	EHGriffith@aol.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203214	WELL	PR	09/01/1985	OW	001-08723	CHAMPLIN (HER) 2-8	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	no containment for chemicals on location, chemicals tanks need proper BMP		
Corrective Action:	Install or repair required BMPs per Rule 1002.f.(2)C		Date: 06/21/2022
Type	OTHER		
Comment:	Stained soil in separator house, motor house, in front of wellhead needs to be removed, trash and chemicals stored in separator house, and motor house needs to be removed, mechanical issues need to be address in separator house, wellhead, and gas motor.		
Corrective Action:	Comply with COGCC housekeeping rules		Date: 07/06/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 203214 Type: WELL API Number: 001-08723 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 12/29/2020Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: annual bradenhead test is not current, contact COGCC engineering, provide monthly monitoring data.06/16/2022Corrective Action: Comply with COGCC annual bradenhead testing rules

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective

Date:

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 6/3/22 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Champlin HER 2-8</p> <p>Company Name- Argonex Company LLC</p> <p>API- 05-001-08723</p> <p>In Adams County Colorado.</p> <p>While there, I observed PR well</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Stained soil in separator house, motor house, in front of wellhead needs to be removed, trash and chemicals stored in separator house, and motor house needs to be removed, mechanical issues need to be address in separator house, wellhead, and gas motor.</p> <p>Comply with COGCC housekeeping rules 7/6/22</p> <p>no containment for chemicals on location, chemicals tanks need proper BMP</p> <p>Install or repair required BMPs per Rule 1002.f.(2)C 6/21/22</p> <p>Annual bradenhead test is not current, contact COGCC engineering, provide monthly monitoring data.</p> <p>Comply with COGCC annual bradenhead testing rules</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	medinaj	06/06/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403068524	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5771072
699504000	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5771069