

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/31/2022

Submitted Date:

06/07/2022

Document Number:

688000645**FIELD INSPECTION FORM**Loc ID 317537 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 7800

Name of Operator: BEREN CORPORATION

Address: 2020 N BRAMBLEWOOD STREET

City: WICHITA State: KS Zip: 67206

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kay, Michael	316-249-7597	kaym@berexco.com	All Inspections

General Comment:

Environmental inspection related to Rem #22340. Flowline abandonment requirements should be met prior to backfilling the cut and cap excavation.

Environmental**Spill/Remediation:**

Comment: [Contact flowline group for flowline abandonment requirements. Wellhead excavations should not be backfilled until any flowline abandonment requirements have been met.](#)

Corrective Action: [Provide documentation of compliance with flowline abandonment rules.](#)

Date: 06/28/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403071034	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773390
688000646	Location photographs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773388