

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/03/2022

Submitted Date:

06/07/2022

Document Number:

701103183

FIELD INSPECTION FORMLoc ID 315465 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230871	WELL	PR	06/01/2020	GW	103-08540	CONTINENTAL 6-22	PR

General Comment:

COGCC Follow Up Inspection Report Summary

Follow up to 4/19/2021 inspection # 701500366

Uncorrected action items

- Meter not calibrated annually. Most recent meter calibration in June 2019.
- Bradenhead access is not present.

During this inspection the following compliance issues were observed:

- Weeds covering location and inside of pits.
- No API# on well sign.
- Storm water erosion of road into location.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Road in poor condition		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	No API# on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	10/08/2022

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds covering location and inside of pits.		
Corrective Action:	Comply with Rule 606	Date:	06/30/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter not calibrated annually. Most recent meter calibration in June 2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 02/01/2021
Type: Bradenhead	# 1		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 02/01/2021

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	230871	Type:	WELL	API Number:	103-08540	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Storm water erosion of road into location.Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)CDate: 06/30/2022**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: <u>Blowdown</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
-----------------------	------------------	---------	------	-------

Reference Point: _____	Other: _____	Length: _____	Width: _____
------------------------	--------------	---------------	--------------

Lining:

Liner Type: _____ Liner Condition: _____

Comment: Well pit.

Corrective Action

Date: _____

Fencing:Fencing Type: Wildlife Fencing Condition: Adequate

Comment: _____

Corrective Action

Date: _____

Netting:Netting Type: Mesh Netting Condition: _____

Comment: _____

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: YESComment: See housekeeping

Corrective Action

Date: _____

Type: <u>Blowdown</u>	Lined: <u>NO</u>	Pit ID:	Lat:	Long:
-----------------------	------------------	---------	------	-------

Reference Point: _____	Other: _____	Length: _____	Width: _____
------------------------	--------------	---------------	--------------

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Corrective Action

Date: _____

Fencing:Fencing Type: Wildlife Fencing Condition: AdequateComment: Separator pit.

Corrective Action

Date: _____

Netting:Netting Type: Mesh Netting Condition: _____

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	See housekeeping	Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403071934	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773960
701103194	Inspection 701103183 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773957