

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/03/2022

Submitted Date:

06/08/2022

Document Number:

701103185

**FIELD INSPECTION FORM**

Loc ID 315538 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10654  
Name of Operator: LASSO OIL & GAS LLC  
Address: 3021 RIDGE RD #156  
City: ROCKWALL State: TX Zip: 75032

**Findings:**

- 9 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
231004	WELL	PR	03/18/1982	GW	103-08673	COORS 8-22	PR

**General Comment:**

[COGCC Follow Up Inspection Report Summary](#)  
Follow up to 04/16/2021 inspection # 701500368  
Uncorrected action items

- Bradenhead access is not present.
- Most recent meter calibration in June 2019. Meter not calibrated annually.
- Erosion channel coming off location that continues downhill on the access road. Part of the channel bypasses the road ditch that channels stormwater off the road. The erosion channels on the road are ~1 foot deep. Also an erosion channel on the side of the access road is present uphill of the location. No rip rap is present.
- Battery sign not present.

During this inspection the following compliance issues were observed:

- No API# on well sign.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No API# on well sign.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	09/08/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not present.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	07/19/2021

Emergency Contact Number:	
Comment:	911
Corrective Action:	
Date:	_____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration in June 2019. Meter not calibrated annually.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).	Date:	02/01/2021
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).	Date:	02/01/2021

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 231004 Type: WELL API Number: 103-08673 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion channel coming off location that continues downhill on the access road. Part of the channel bypasses the road ditch that channels stormwater off the road. The erosion channels on the road are ~1 foot deep. Also an erosion channel on the side of the access road is present uphill of the location. No rip rap is present.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/19/2021

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition:

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

**Netting:**

Netting Type:    Netting Condition:

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

Anchor Trench Present:                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat:                      Long:

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type:    Liner Condition:

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

**Fencing:**

Fencing Type: Wildlife    Fencing Condition:

Comment: \_\_\_\_\_  
 Corrective Action \_\_\_\_\_

Date:

<b>Netting:</b>		
Netting Type:	Netting Condition:	
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action	<input style="width: 100%;" type="text"/>	
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:	<input style="width: 100%;" type="text"/>	
Corrective Action	<input style="width: 100%;" type="text"/>	
		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403071937	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773962">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773962</a>
701103196	Inspection 701103185 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773959">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5773959</a>