

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/09/2022

Submitted Date:

06/09/2022

Document Number:

699504016

**FIELD INSPECTION FORM**Loc ID 320023 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 71450

Name of Operator: PONCHO PRODUCTION COMPANY

Address: 5299 DTC BLVD #1300

City: GREENWOOD State: CO Zip: 80111

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Vaclavik, Robert	(866) 767-3600	rpvacvik@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202293	WELL	PR	06/01/2021	GW	001-07698	PERKINS-THORNBURG 1	PR

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Mechanical issue with separator, stained soil, weeds unmanaged on location, storage of fiberglass tank on location

Corrective Action:

Comply with COGCC housekeeping rules 4/2/21

Date: 04/02/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Prime Mover

# 1

Comment:

electric motor

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment:

plumbed to surface

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

electric

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

# 1

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER	1	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:		shares containment with oil tank				
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST			
Comment:						
Corrective Action:					Date:	
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 202293 Type: WELL API Number: 001-07698 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 12/19/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On 6/8/22 I, Inspector Justin Medina conducted an on-site inspection at:</p> <p>Well Name- Perkins-Thornburg 1</p> <p>Company Name- Poncho Production Company</p> <p>API- 05-001-07698</p> <p>In Adams County Colorado.</p> <p>While there, I observed PR well</p> <p>This is a follow up inspection from document # 699502343 Corrective Actions are Delinquent</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Mechanical issue with separator, stained soil, weeds unmanaged on location, storage of fiberglass tank on location</p> <p>Comply with COGCC housekeeping rules 4/2/21</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This inspection does not nullify any orders or NOAV from the COGCC.</p> <p>This is a summary of inspection report.</p>	medinaj	06/09/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403074163	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775497">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775497</a>
699504017	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775491</a>