

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	pump jack is leaning forward towards the west, rods are strained and beginning to bend towards the west, this may cause a well control issue if rods are to part or pump jack is to slide into wellhead		
Corrective Action:	Comply with COGCC housekeeping rules	Date:	07/09/2022
Type	OTHER		
Comment:	Berms on locaiton are not adequate, animal burrows and erosion		
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).	Date:	06/24/2022

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	4' barb wire		
Corrective Action:		Date:	

Equipment:

Type		#		corrective date
Horizontal Heated Separator		# 1		
Comment:				
Corrective Action:				Date:
Bradenhead		# 1		
Comment:	plumbed to surface			
Corrective Action:				Date:
Prime Mover		# 1		
Comment:	electric motor			
Corrective Action:				Date:
Pump Jack		# 1		
Comment:				
Corrective Action:				Date:
Ancillary equipment		# 1		
Comment:	electric			
Corrective Action:				Date:

Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV FIBERGLASS		,
Comment:	80 BBL				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	needs maintenance			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	needs mainenance			
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201257 Type: WELL API Number: 001-06660 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 11/02/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 6/8/22 I, Inspector Justin Medina conducted an on-site inspection at: Well Name- UPRR Walker 1-29 Company Name- Renegade API- 05-001-06660 In Adams County Colorado. While there, I observed SI well During this inspection the following possible compliance issues were observed: pump jack is leaning forward towards the west, rods are strained and beginning to bend towards the west, this may cause a well control issue if rods are to part or pump jack is to slide into wellhead Comply with COGCC housekeeping rules 7/9/21 Berms on location are not adequate, animal burrows and erosion. Repair or install berms or other secondary containment devices per Rule 906.d.(1). A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This inspection does not nullify any orders or NOAV from the COGCC. This is a summary of inspection report.</p>	medinaj	06/09/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403074166	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775500
699504023	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5775494