

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500077

FIELD INSPECTION FORM

Loc ID 325784 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215375	WELL	PR	05/06/2021	GW	067-06980	MAYFIELD MELTON 1	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location

Overall Good:

Emergency Contact Number:

Comment: [Emergency contact listed on well sign on north side of gas meter house. 24 hr contact: 970-247-6916 and Emergency Contact: 911](#)

Corrective Action:

Date:

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused metal panels on west side of pump jack (IMG 03). AWS workover rig sign is no longer in use, as well as unused metal debris next to it (IMG 06).		
Corrective Action:	Use or remove equipment per rule 606.	Date:	07/01/2022
Type	WEEDS		
Comment:	Weeds beginning to encroach on pump jack within steel mesh enclosure (IMG 04).		
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Pump jack, separator, gas meter house, and telemetry are each enclosed by stock panel.		
Corrective Action:		Date:	

Equipment:

Type			corrective date
Type: Flow Line	# 5		
Comment:	3" line from wellhead to separator, 2" produced water line from separator to off location, 3" gas line from separator to gas meter house, 2 2" lines from gas meter house to off location.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	One rig anchor is knocked down (IMG 05).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/01/2022

Type: Ancillary equipment	# 2		
Comment:	Telemetry, pump control panel		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Electric prime mover		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	Separator vent stack is enclosed properly.		
Corrective Action:			Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 215375 Type: WELL API Number: 067-06980 Status: PR Insp. Status: PR

Producing Well

Comment: [Pump jack operating intermittently during inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500078	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781475