

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500081

FIELD INSPECTION FORM

Loc ID 306916 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277747	WELL	PR	10/15/2021	GW	067-09044	MAYFIELD MELTON 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
	Type Access		
comment:	Gravel access road is overgrown by weeds (IMG 03).		
Corrective Action:	Control weeds per rule 606.	Date:	07/01/2022
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	Emergency contact listed on well sign. 24 hr contact: 970-247-6916. Emergency contact: 911		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	OTHER		
Comment:	Pump jack enclosed by stock panel. Separator, gas meter house, and produced water tank enclosed by stock panel.		
Corrective Action:		Date:	
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric prime mover		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Vertical heated separator vent stack is enclosed properly.		
Corrective Action:		Date:	
Type: Flow Line	# 3		

Comment:	3" line from wellhead to separator, line from separator to produced water tank, 4" line from gas meter house to off location.				
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 5				
Comment:	Telemetry, electric shut off panel, electric meter panel, electric cabinet, and pump control panel.				
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.128747,-107.776543
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Buried metal secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		
		Date:

Flaring:

Type		
Comment:		
Corrective Action:		
		Date:

Inspected Facilities

Facility ID: 277747 Type: WELL API Number: 067-09044 Status: PR Insp. Status: PR

Producing Well

Comment: [Pump jack operating intermittently during inspection.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					Ditch along west and south side of location
Culverts	Pass					Culverts along access road

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500082	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781476