

Inspection Photos

API: 071-06037

Operator: OXY USA INC

Inspection Date: 6/16/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 1. Facing southeast along the access road near Compressor facility. There is damaged culvert that need to be removed. Additionally vehicles are driving on the road at red arrow instead of the access road at the left due to damaged cattleguard. Vehicle must stay on original access road boundary. Additional disturbance will need to be reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 2. The cattle guard is damaged and needs to be repaired or removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 3. There are noxious weeds along the access road that need to be controlled.
Red arrow → Canada thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 4. Facing southeast toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 5. There is gravel debris from a pile stored on location. The leftover gravel needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022

Inspection Photos



Photo 6. There are still degraded wattles on the cut slope that need to be removed. There are noxious weeds in this area that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06037 | Date: 6/16/2022