

Inspection Photos

API: 055-06041

Operator: OXY USA INC

Inspection Date: 6/16/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 1. Facing southwest along the access road near the SMU #1-12-B . There is erosion in this area that needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 2. Facing southwest along the access road near the SMU #1-12-B . There is erosion in this area that needs to be repaired and stabilized. There is also noxious weeds in this area of the road that need to be controlled. Observed Canada thistle and Hoary crest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 3. Facing southwest along the road. This area is rutted out and needs stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 4. There is a flowline riser along the road which is Locked out. The riser needs to be identified per 1102.g.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 5. Facing southwest along the steep area of the road. There is erosion along this area due to stormwater not properly diverted off the road. This area needs to be repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 6. Facing west toward the well site. The location is fully vegetated and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 7. Facing southeast toward the well site. The location is fully vegetated and stabilized. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 8. Facing north along the fill slope. There are noxious weeds in this area that need to be controlled. Red arrow → Canada thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022

Inspection Photos



Photo 9. Facing north at the cut slope of the location. There are numerous noxious weeds in this area that need to be controlled. This area needs to be reseeded.
Red arrow → Canada thistle



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06041 | Date: 6/16/2022