

**TEP  
RWF 331-11  
Location # 335638**




**location**



**location**

**TEP  
RWF 331-11  
Location # 335638**



**location**



**location**

**TEP  
RWF 331-11  
Location # 335638**



**Valves on tanks missing caps/ plugs**




**Valves on tanks missing caps/ plugs**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**TEP  
RWF 331-11  
Location # 335638**



**Valves on tanks missing caps/ plugs**



**Lack of stabilization/ compaction**

**TEP  
RWF 331-11  
Location # 335638**



**Erosion**



**Erosion**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**TEP  
RWF 331-11  
Location # 335638**



**Erosion**



**Erosion**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**TEP  
RWF 331-11  
Location # 335638**



Jun 15, 2022 at 11:29:59 AM  
39.543285, -107.850973 ±4.70m  
COGCC

**Erosion and subsidence**



Jun 15, 2022 at 11:30:19 AM  
39.543285, -107.850973 ±4.70m  
COGCC

**Erosion**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**TEP  
RWF 331-11  
Location # 335638**



**Erosion**



**Erosion and subsidence**

**TEP  
RWF 331-11  
Location # 335638**



**Lack of stabilization/ compaction**



**Lack of stabilization/ compaction/ Hard hat in rutting**