

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/17/2022

Submitted Date:

06/20/2022

Document Number:

702500101

FIELD INSPECTION FORMLoc ID 326440 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, General		regulatory@logosresourcesllc.com	All SW field inspections
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	All SW field Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216494	WELL	PR	07/01/2019	GW	067-08100	BONDAD 33-9 25A	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Emergency contact number listed on well sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused metal tubing near separator (IMG 08).			
Corrective Action:	Use or remove unused equipment per rule 606.			Date: 07/03/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	OTHER			
Comment:	Wellhead enclosed by wire fencing. Produced water tank and separator enclosed by wire fencing.			
Corrective Action:				Date:
Equipment:				
Type: Horizontal Heated Separator	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 3			
Comment:	2" line from wellhead to separator, 2" line from separator to produced water tank, 2" line from produced separator to off location			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	Rig anchors are less than 4' (IMG 04, IMG 05, IMG 06, IMG 07).			
Corrective Action:	Install proper guy line markers per Rule 1003.a			Date: 07/03/2022
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	Horizontal heated separator vent stack screened properly.			
Corrective Action:				Date:

Type: Bradenhead	# 1	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Telemetry	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	PBV STEEL		37.122924,-107.843803
Comment:	Partially buried produced water tank.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	produced water
Other (Capacity)	125 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:	Berm height appears insufficient (IMG 09).			
Corrective Action:	Confirm secondary containment capacity is adequate. If not repair secondary containment devices per Rule 912.d.(1).			Date: 07/08/2022

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216494	Type:	WELL	API Number:	067-08100	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:									
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702500102	photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5783448