

Inspection Photos  
Operator: Rim Operating  
API: 067-09814  
Date: 6/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, smooth brome and crested wheatgrass.





Photo 3. View of area downslope of cobble BMP in the southeastern project area, where erosional channeling continues (approx 12-15 inches wide and deep) and additional stabilization is needed. Wattle is no longer functioning.





Photo 4. View of area within the northeastern project area where wattles are full of sediment and need replacement and continued maintenance.





Photos 5-7. View of musk thistles within the project area. Approximately 250-350 individuals observed.





Photo 8. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, sagebrush, serviceberry, Indian ricegrass, and Palmer's penstemon.