

Inspection Photos
Operator: Rim Operating
API: 067-09286
Date: 6/13/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, rubber rabbitbrush, smooth brome and crested wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of erosional headcutting and channeling (inset) within the southwestern corner of the project area where diverted stormwater flows off of the well pad (approx. 2-3ft wide and deep).



Photo 5. View of stained soils approximately 6 ft wide and long, within the eastern project area.



Photos 6. View of Canada thistles (yellow arrows) observed within the project area, approximately 50 Canada and musk thistles observed.



Photo 7. View of reference area comprised of pinyon and juniper woodland with gambel oak, mountain mahogany, sagebrush, serviceberry, Indian ricegrass, and Palmer's penstemon.