

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/16/2022

Document Number:

688000649

**FIELD INSPECTION FORM**Loc ID 312327 Inspector Name: YOUNG, ROB On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 11001

Name of Operator: BROWN OIL &amp; GAS LLC

Address: 10481 COUNTY ROAD 20.5

City: STERLING State: CO Zip: 80751

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                     | Comment |
|--------------|-------|---------------------------|---------|
| ,            |       | brownoilandgas1@gmail.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name         | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 284011      | WELL | SI     | 10/01/2018  | OW         | 075-09351 | CEDAR CREEK RANCH 1-Y | EI          |

**General Comment:**

Environmental inspection related to Rem #19018, see CAs.

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 284011 | Type: | WELL | API Number: | 075-09351 | Status: | SI | Insp. Status: | EI |
|                      |        |       |      |             |           |         |    |               |    |

|  |
|--|
|  |
|--|

**Environmental****Spill/Remediation:**

Comment: [All equipment has been removed from the location since the previous environmental inspection.](#)

Corrective Action: [Provide an up to date soil sample location map, analytical data summary table and a revised implementation schedule for sampling the produced water pit and other required remediation.](#)

Date: 06/30/2022

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403082607    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782520">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782520</a> |
| 688000650    | Location photographs | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782512">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782512</a> |