

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500076

FIELD INSPECTION FORM

 Loc ID 326566 Inspector Name: Klink, Alex On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10749
 Name of Operator: SIMCOE LLC
 Address: 1199 MAIN AVE SUITE 101
 City: DURANGO State: CO Zip: 81301
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 22 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, General		sjninspections@ikavenergy.com	All SW field inspections
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258061	WELL	PR	05/23/2016	GW	067-08320	SOUTHERN UTE ALLOTTEE BC 2	PR
444658	SPILL OR RELEASE	CL	01/25/2016		-	SPILL/RELEASE POINT	CL

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Emergency Contact Number:			
Comment:	Emergency contact listed at location entrance. Emergency contact: 970-247-6916 or 911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Fill dirt pile on southwest corner of location (IMG 09).		
Corrective Action:	Remove stored supplies per rule 606.		Date: <u>08/15/2022</u>
Type	DEBRIS		
Comment:	Unused chair and debris on northwest corner of location (IMG 06). Also post with concrete base is not in use on west side of location (IMG 08).		
Corrective Action:	Remove debris to comply with rule 606.		Date: <u>06/23/2022</u>
Type	OTHER		
Comment:	Lube oil on wellhead has begun to impact surface material around wellhead (IMG 04, IMG 05).		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	LOCATION		
Comment:	Location enclosed by chain link fence with barbed wire.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Produced water tank is enclosed by stock panel.		
Corrective Action:			Date:
Equipment:			
Type: Vertical Heated Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 5		
Comment:	Telemetry, PLC speed control panel, VFD panel, enclosed transfer pump west of separator, pump control panel north of pump jack		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead is accessible.		
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	2" line from wellhead to separator, 3" line from separator to meter house, line from separator to produced water tank, 2" line from separator to unknown location.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric prime mover		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Vertical separator vent stack is enclosed properly.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Rig anchor in southwest corner is not marked (IMG 07).		
Corrective Action:	Install proper guy line markers per Rule 1003.a	Date:	07/01/2022
Type: Gas Meter Run	# 1		
Comment:	Meter calibration current within last year.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV STEEL		37.181247,-107.755547
Comment:	Partially buried produced water tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	Produced Water
Other (Capacity)	21 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Partially buried metal secondary containment.			
Corrective Action:				Date:

Venting:

Yes/No	
--------	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 258061 Type: WELL API Number: 067-08320 Status: PR Insp. Status: PR

Producing Well

Comment: Pump jack running intermittently during inspection.

Corrective Action:

Date:

Facility ID: 444658 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					Ditch along west edge of location
Berms	Pass					Run on berms

Comment: [No observed impact of storm water. Storm water controls seem sufficient at time of report.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403081589	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781479
702500080	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781474