

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500083**FIELD INSPECTION FORM**Loc ID 333762 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268038	WELL	PR	05/21/2003	GW	067-08819	LILA CUMMINS A 2	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	OTHER			
Comment:	Produced water tank sign is not secured properly (IMG 10). Tank capacity is not listed.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 07/08/2022
Emergency Contact Number:				
Comment:	Emergency contact listed on well sign. 24 hr contact: 970-247-6916. Emergency contact: 911			
Corrective Action:				Date:
Good Housekeeping:				
Type	WEEDS			
Comment:	Extensive weeds are present around produced water tank (IMG 11).			
Corrective Action:	Control weeds to comply with rule 606.			Date: 07/01/2022
Type	UNUSED EQUIPMENT			
Comment:	Unused stock panel and unused tarp near A2 wellhead (IMG 07 and IMG 08).			
Corrective Action:	Use or remove equipment to comply with rule 606.			Date: 07/01/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Well A2 is enclosed on 3 sides by sound panels, and stock panel on 4th side.			
Corrective Action:				Date:
Equipment:				
			corrective date	
Type: Flow Line	# 3			
Comment:	1 4" lines from wellhead to separator house, 2" line from separator to produced water tank, 4" line from produced water tank.			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Bradenhead is accessible.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	Produced water vent stack is properly enclosed.			

Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Telemetry and electric panel enclosed in cabinet near separator house, electric meter		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration is current within last year.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	3 Vertical heated separators and 3 gas meter runs are all enclosed in one house near produced water tank. Other equipment is associated with Lila Cummins A3 and A4 wells.		
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		PBV STEEL		37.137128,-107.720093
Comment:	Produced water tank.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	
Other (Type)	Cone top

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Double walled tank.			
Corrective Action:			Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	268038	Type:	WELL	API Number:	067-08819	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Free flowing wellhead with compressor station.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts	Pass					Culverts on access road
Rip Rap	Pass					Rip rap run off

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403081592	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781482
702500084	Photo doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781477