

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/15/2022

Submitted Date:

06/16/2022

Document Number:

702500085**FIELD INSPECTION FORM**Loc ID 333999 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10749Name of Operator: SIMCOE LLCAddress: 1199 MAIN AVE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
, General		sjninspections@ikavenergy.com	All SW field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
297205	WELL	PR	07/16/2008	GW	067-09602	LILA CUMMINS A 3	PR
297886	WELL	PR	06/28/2021	GW	067-09617	LILA CUMMINS A 4	PR

General Comment:

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Emergency contact listed on well sign. 24 hr contact: 970-247-6916. Emergency contact: 911			
Corrective Action:				Date:
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds are present in enclosure around pump jacks A3 and A4 (IMG 05, IMG 06).			
Corrective Action:	Control weeds to comply with rule 606.			Date: 07/01/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Pump jacks enclosed by metal fencing.			
Corrective Action:				Date:
Equipment:				
				corrective date
Type: Prime Mover	# 2			
Comment:	2 electric prime movers			
Corrective Action:				Date:
Type: Ancillary equipment	# 4			
Comment:	Telemetry and electric panel enclosed in cabinet near separator house, electric meter, 2 pump control panels at pump jacks.			
Corrective Action:				Date:
Type: Flow Line	# 6			
Comment:	2 4" lines from wellhead to separators, 2" line from separator to produced water tank, 4" line from produced water tank, 2 2" lines off gas supply line before separator house,			
Corrective Action:				Date:
Type: Pump Jack	# 2			
Comment:				
Corrective Action:				Date:
Type: Vertical Heated Separator	# 2			
Comment:	3 Vertical heated separators and 3 gas meter runs are all enclosed in one house near produced water tank. Other equipment is associated with Lila Cummins A2 well.			

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Produced water vent stack is properly enclosed.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Bradenheads are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Gas meter calibrations are current within last year.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		PBV STEEL		37.137128,-107.720093	
Comment:	Produced water tank.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Double walled tank.			
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 297205	Type: WELL	API Number: 067-09602	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:
Facility ID: 297886 Type: WELL API Number: 067-09617 Status: PR Insp. Status: PR				

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Rip Rap						

Comment: No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403081593	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781483
702500086	Photo Doc	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5781478