

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2022

Submitted Date:

06/16/2022

Document Number:

702500087**FIELD INSPECTION FORM**Loc ID 326465 Inspector Name: Klink, Alex On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**20 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Walker, Mandi		mwalker@hilcorp.com	<a href="#">All SW field inspections</a>
Shorty, Priscilla	505-324-5188	pshorty@hilcorp.com	<a href="#">All SW filed inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216544	WELL	PR	09/11/1998	GW	067-08150	DAVIS 2-5	PR

**General Comment:**

Inspector Alex Klink on site to conduct routine inspection. Any corrective actions from previous inspections are still applicable. See link at end of report for inspection photos.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Compacted gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:	Emergency contact listed on well sign.			
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	TRASH			
Comment:	Tarp near pump jack (IMG 04) and poly tubing near compressor house (IMG 09).			
Corrective Action:	Remove trash to comply with rule 606.			Date: 07/16/2022
Type	STORAGE OF SUPL			
Comment:	Unused stock panels near produced water tank (IMG 06).			
Corrective Action:	Use or remove unused equipment per rule 606.			Date: 07/16/2022
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Pump jack is enclosed by metal mesh fencing, and prime mover generator is enclosed on 2 sides by sound panels.			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Compressor	# 2			corrective date
Comment:	2 compressors located in compressor house.			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	Last gas meter calibration was 4/13/21 (IMG 05).			
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).			Date: 07/16/2022
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	1 rig anchor with marker, 3 rig anchors with markers not secured properly (IMG 10, IMG 11, IMG 12).			
Corrective Action:	Install proper guy line markers per Rule 1003.a			Date: 07/19/2022

Type: Other	# 1	
Comment:	Tracer line wire in 1" poly line near separator	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	Bradenhead is accessible.	
Corrective Action:		Date:
Type: Flow Line	# 8	
Comment:	In use: 2 3" lines from wellhead to separator, 1" gas supply line from separator to prime mover generator, 4" line from separator to gas meter run, 3" line from separator to produced water, 4" line from gas meter run to compressor house.  Not in use: 1" flow line uncapped near separator (IMG 08), 1" flow line uncapped near pump jack (IMG 03).	
Corrective Action:	Apply Out of Service Locked and Tagged on unused flow line per rule 1101.(3)	Date: 07/19/2022
Type: Ancillary equipment	# 3	
Comment:	Telemetry, electric panel, electric meter	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Gas powered prime mover.	
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:	3 produced water tank vents and separator vent stack are screened.	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	1000 BBLS	STEEL AST		37.246777,-107.764242
Comment:	3 produced water tanks, each with 1000 bbl capacity.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	Produced water
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Metal secondary containment for tanks. Each tank has additional metal berm around base.			
Corrective Action:				Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

<b>Inspected Facilities</b>				
Facility ID: 216544	Type: WELL	API Number: 067-08150	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:				
Corrective Action:				Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Compaction	Pass			
Waddles	Pass					
Compaction	Pass					
Berms	Pass					
Rip Rap	Pass					
Ditches	Pass					
Check Dams	Pass					
Gravel	Pass					
Check Dams	Pass					

Comment: Multiple stormwater control techniques observed. No observed impact of storm water. Storm water controls seem sufficient at time of report.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**    ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403082604	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782517">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782517</a>
702500097	photo doc	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782513">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5782513</a>