

Today's Date:	5/26/2022					
Well Name:	ALLISON UNIT 147	Location:	Sec: 24	Twn: 032N	Rng: 007W	UL: N
API Number:	05.067.08350	Footage:	800' FSL & 1849' FWL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0509	Brian Van Caster	
Meter #:	8268301		Pipeline:	HAR		
INC Number:	693904553	Agency:	COGCC	Inspector:	Catherine Roy	
Type of INC:	Written	Photos Required:	Yes	Due Date:	6/30/2022	
Issue of Concern:	<p>On 5/24/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:</p> <p>-Control weeds. Due to the extent of the infestation a treatment plan is needed and multiple treatments will likely be needed. Seeding in treatment areas may be needed after infestation is controlled. Corrective action date: 6/30/2022</p> <p>See below, and attached photos for additional detail.</p> <p>Thousands of Russian knapweeds observed within the interim reclamation areas and along the western access road.</p> <p>-Control weeds. Due to the extent of the infestation a treatment plan is needed and multiple treatments will likely be needed. Seeding in treatment areas may be needed after infestation is controlled. Corrective action date: 6/30/2022</p>					







